



Worldwide repairs carried out with PolymerMetal®

REP-# 062



The repair of a crack on the drying drum of a cotton spinning machine was carried out with MM-metal SS-steelceramic and Hardener yellow. Data: steam pressure 3 bar, steam temperature 180 - 240 °C.

MultiMetal
the MetalExistenceCompany®