




Worldwide repairs carried out with PolymerMetal[®]

REP-# 006



Repair of several bilge pumps and fire pumps (type Loew VZLG 65/1/2, power 60 m³/h) with Ceramium pasty and Ceramium liquid. An inspection 3 years after the repair did not show any faults or objections at the repaired object.

MultiMetall
the MetalExistenceCompany[®]