



Worldwide repairs carried out with PolymerMetal<sup>®</sup>

REP-# 025



Repair of four cracks on the cylinder block of a big engine called „Super MAZ“ were repaired with MM-metal SS-steelceramic and Hardener yellow. One of the cracks passed the oil channel and was therefore sealed with MM-metal oL-steelceramic and Hardener red.

**MultiMetall**  
the MetalExistenceCompany<sup>®</sup>