




Worldwide repairs carried out with PolymerMetal®

REP-# 112



Corrosion and abrasion damages on high pressure fan casings in a paper-mill have been removed using Ceramium pasty and Hardener CE.

MultiMetal
the MetalExistenceCompany®